

| | | | | |
|--|------------------------------------|--|--|-------------------------------|
| <i>Mon, Jul 7</i> | <i>2pm – 4pm</i> | AQUIS Team arrives to meet with Customer and setup equipment and material | | |
| <i>Tue, Jul 8</i> <i>5pm – 2am</i> AQUIS Coatings | <i>Bldg 082</i> | <i>AHU-16, AHU-17</i> | <i>Coil Restoration +</i> | |
| | <i>Bldg 083</i> | <i>AHU-3, AHU-9</i> | <i>Coil Restoration</i> | |
| <i>Wed, Jul 9</i> <i>5pm – 2am</i> AQUIS Coatings | <i>Bldg 082</i> | <i>AHU-18</i> | <i>Coil Restoration +</i> | |
| | <i>Bldg 082</i> <i>Bldg 083</i> | <i>AHU-19, AHU-20, AHU-26 AHU-3</i> | <i>Coil Restoration</i> <i>AQUIS Coatings</i> | |
| <i>(No MVS Foster 40-20)</i> | | | | |
| <i>Thu, Jul 10</i> <i>5pm – 2am</i> | <i>Bldg 082</i> | <i>AHU-27, AHU-4, AHU-1120</i> | <i>Coil Restoration</i> | |
| | <i>Bldg 082</i> <i>Bldg 083</i> | <i>AHU-16, AHU-17, AHU-18 AHU-3</i> | <i>AQUIS Coatings</i> | <i>AQUIS Coatings</i> |
| <i>(No MVS Foster 40-20)</i> | | | | |
| <i>Fri, Jul 11</i> | | | | |
| <i>10am – 4pm</i> | | <i>Bldg 91</i> | <i>ERU-1, ERU-2, ERU-3</i> | <i>Coil Restoration *Only</i> |
| <i>one ERU can be down at a time*</i> | | | | |
| <i>5pm – 2am</i> | <i>Bldg 082</i> | <i>AHU-19, AHU-20</i> | <i>AQUIS Coatings</i> | |
| <i>Sat, Jul 12</i> | | | | |
| <i>5pm – 2am</i> | <i>Bldg 082</i> | <i>AHU-26, AHU-27</i> | <i>AQUIS Coatings</i> | |
| | <i>Bldg 91</i> | <i>AHU-91-01</i> | <i>Coil Restoration</i> | |